

FIG. 1




FIG. 2




FIG. 3 A




FIG. 3 B




FIG. 4 A

RECEIVED SIGNAL WITH NO FREQUENCY ERROR




FIG. 4 B

RECEIVED SIGNAL WITH A CARRIER FREQUENCY ERROR




FIG. 4 C

RECEIVED SIGNAL WITH A CLOCK FREQUENCY ERROR




FIG. 5




FIG. 6




FIG. 7





FIG. 8



F I G . 9




FIG. 10

